# Laser PM100 Sensor specification

**Product model: SDS198** 

Version: V1.2



Nova Fitness Co.,Ltd 2015-10-8

## Contents

OVERVIEW	1
CHARACTERISTICS	1
SCOPE OF APPLICATION	2
WORKING PRINCIPLE	2
Technical parameters	2
POWER REQUIREMENT	4
About service life	4
Product specifications	4
1.Product size	4
2.Interface specification	5
THE UART COMMUNICATION PROTOCOL	5
EXTENDED FUNCTIONALITY	
INSTALLATION SIZE	7
Package	9
MATTERS NEEDING ATTENTION	9
CONTACT	10

## **Overview**

The PM100 sensor, also known as total suspended particulate (TSP) sensor, using principle of laser scattering, can get the particle concentration between 1 to 100µm in the air. The SDS198 with digital output and built-in fan is stable and reliable.



## **Characteristics**

- 1. Accurate and Reliable: laser detection, stable, good consistency;
- 2. Quick response: response time is less than 10 seconds when the scene changes;
- 3. Easy integration: UART output (or IO output can be customized), fan built-in;

1



- 4. High resolution: resolution of 1µg/m<sup>3</sup>;
- 5. Certification: products have passed CE/FCC/RoHS certification.

## Scope of application

TSP monitoring; Dust monitoring; Purification monitoring; Environmental monitoring of road, factory, mine, and construction site.

# Working principle

Using laser scattering principle:

Light scattering can be induced when particles go through the detecting area. The scattered light is transformed into electrical signals and these signals will be amplified and processed. The number and diameter of particles can be obtained by analysis because the signal waveform has certain relations with the particles diameter.

# **Technical parameters**

2

No	Item	Parameter	Note
1	Measurement parameters	PM100	
2	Range	$0-20 \text{mg/m}^3$	
3	Rated voltage	5V	
4	Rated current	70mA±10mA	
5	Sleep current	<4 mA	Lase&Fan sleep
6	Tomporatura ranga	Storage environment: -20 ~ +60 °C	
	Temperature range	Work environment: $-10 \sim +50$ °C	
7	Humidity range	Storage environment: Max 90%  Work environment: Max 70%	
8	Air pressure	86KPa~110KPa	
9	Corresponding time	< 6s	
10	Serial data output frequency	1Hz	
11	Sensitivity	$1 \mu g / m^3$	
12	Relative error	Maximum of $\pm 20\%$ and $\pm 30\mu g/m^3$	25℃, 50%RH
13	Product size	71x70x23mm	
14	Certification	CE/FCC/RoHS	



## **Power requirement**

Power Voltage: 4.7~5.3V

Power supply: >1W

Supply voltage ripple: <20mV

### **About service life**

Service life is the key parameter of laser dust sensor. The laser diode in this sensor has high quality and its service life is up to 8000 hours. If you need real-time data (such as detector), you can use the default configuration that measures at the frequency of 1time per second. On the occasion of real-time demand is not high (such as filter, air quality monitoring, etc.), you can use the discontinuous working method to prolong the service life. For example, you can start the sensor for 30 seconds per minutes. If you have any other requirements, please contact us, we are willing to serve for manufacturers and developers.

# **Product specifications**

#### 1.Product size

L\*W\*H=71\*70\*23mm



## 2.Interface specification

No	Name	Comment	
1	NC	Not Connect	
2	1μm	Reserved	
3	5V	5V Input	
4	2.5µm	Reserved	
5	GND	Ground	
6	R	RX of UART (TTL) @3.3V	
7	Т	TX of UART (TTL) @3.3V	

PS: The distance between each pin is 2.54mm.

# The UART communication protocol

Bit rate: 9600

Data bit: 8

Parity bit: NO

Stop bit: 1

Data Packet frequency: 1Hz

The number of bytes	Name	Content
0	Message header	AA
1	Command Byte.	CF
2	DATA 1	Reserved
3	DATA 2	Reserved
4	DATA 3	PM100 Low byte
5	DATA 4	PM100 High byte
6	DATA 5	ID byte 1
7	DATA 6	ID byte 2
8	Check-sum	Check-sum
9	Message tail	AB

Check-sum: Check-sum=DATA1+DATA2+...+DATA6.

PM100 value:PM100( $\mu$ g/m³)=PM100 High byte\*256+PM100 low byte

# **Extended functionality**


- 1. Manual hibernation(Sleep and wake up)
- 2.Timed hibernate(Cycle to work)
- 3.User ID setting
- 4. Set data reporting mode(Active report and query report)
- 5. Version number query

If you have any other requirements, please contact us.





## **Installation size**

#### 1. Basic structure




## 2. Basic dimensions





3. Recommended installation direction



- 4. Hose connection: optional. It can be connected with the hose of 6mm inner diameter and 8mm external diameter. The hose cannot be longer than 1m, the shorter the better. The hose must keep the air flowing.
  - 5. Prevent glare: the sensor has shading device inside, so it



can work normally under the common light. You should pay attention to prevent the inlet, outlet from direct light.

6. Keep the inlet and outlet unobstructed.

# **Package**



There are 24 sensors on each floor



Each box:4×24=96

# **Matters needing attention**

- 1. In the context of the sensor power supply;
- 2. Note the process design to ensure smoothness and stability of sensor airflow;

- 3. Please ensure that the sensor to work under normal conditions of temperature and humidity;
- 4. Avoid severe vibration during transport, so as not to affect the accuracy of detection and accuracy;
- 5. Follow this specification is the correct sensor installation.

## **Contact**

Nova Fitness Co.,Ltd

TEL: +86-0531-82868288

FAX: +86-0531-82868198

www.inovafitness.com